

PAGE 1 OF 7

PROJECT	San Jacinto River Waste Pits TCRA Post Hurricane Harvey Inspection and Maintenance			CONTRACT NO.		
CONTRACTOR	USA Environment, LP (USA) – Maintenance Hydrographic Consultants (HC) – Survey Benchmark Ecological Services (BESI) – Inspection			SUPERINTENDENT	Mike Wells (USA)	
DAY OF WEEK & DATE: Thursday, September 7, 2017			7	REPORT NO.	4	
WEATHER	Sunny; winds out of NNE			TEMPERATURE	L: 65 H: 81 F	
NUMBER/CLASS OF CONTRACTOR'S PERSONNEL:			MAJOR EQUIPMENT ON JOB (Size/capacity and hours):			
5 – USA			Skid Steer – SVL 90-2			
5 – HC			Link Belt 210 X2 Hydraulic Excavator			
3 – BESI			3 @ 12-cy dump trucks			
			on trucks			
TIDE INFORMATION:			HEALTH AND SAFETY INFORMATION:			
Time: 0800	Height:	2.00 NAVD 88	No incidents or near misses on this date.			

CHRONOLOGICAL ACCOUNT OF DAY'S WORK:

0730 - AQ representative on site

0815 – first round (3 trucks) arrive to deliver rock from Bluebonnet stockpile; USA continued maintenance of south & central berms

0905 - BESI and AQ probing west and northwest area

0955 – second round (3 trucks) arrive to deliver rock from Bluebonnet stockpile

1040 – 20-ton truck (1 truck) onsite to deliver rock from quarry in Marble Falls, TX

1050 – HC surveying west cell (topo) and east cell (hydro)

1055 – 20-ton truck (1 truck) onsite to deliver rock from quarry in Marble Falls, TX

1115 – 20-ton trucks (2 trucks) onsite to deliver rock from quarry in Marble Falls, TX

1135 – third round (3 trucks) arrive to deliver rock from Bluebonnet stockpile

1200 – NCS representatives (2 people) onsite to inspect damaged camera systems

1245 – NCS completed inspection of damaged camera systems and departed site

1320 – fourth round (3 trucks) arrive to deliver rock from Bluebonnet stockpile

1510 – fifth round (3 trucks) arrive to deliver rock from Bluebonnet stockpile



PAGE	2	OF	7
FAGE	_	Oi	,

1630 –survey crews and probing crew depart site

1700 – USEPA departs site; AQ departs site; USA departs site

Summary of Progress on this Date:

- Completed initial hydrographic and topographic survey
- Continued cap probing inspection
- Continued maintenance of berms, placing geotextile and rock
- 15 loads of rock received from Bluebonnet stockpile, approximately 250 tons
- 4 loads of rock received from quarry in Marble Falls, approximately 80 tons

Additional Persons Onsite on this Date:

Wendell Mears, Rick Coupe, Justin Marks, John Laplante and David Keith (AQ) Gary Miller and Ashley (USEPA) NCS inspecting damaged camera systems

Material Delivery Summary as of this Date: None.

Material	Units	Delivery (tons)	Delivery Verification Method	Preceding Delivered Total	Total Delivered for Project
Type C	Tons	0	Truck Measure	0	0
Type D	Tons	330	Truck Measure	400	730

TESTS PERFORMED:	None
PHONE LOG:	

SITE PHOTOS/VIDEOS TAKEN:			FORCE ACCOUNT WORK/ CHANGES ENCOUNTERED:					
See attached			None					
QA REPRESENTATIVE	Justin Marks		HRS	8	DATE	9/7/2017		



PAGE 3 OF 7



Photo 1 – probing inspection



Photo 2 – topographic survey activities



PAGE 4 OF 7



Photo 3 – rock delivery



Photo 4 – probing inspection



PAGE 5 OF 7



Photo 5 – southern berm crest maintenance



Photo 6 – hydrographic survey activities



PAGE 6 OF 7



Photo 7 – rock delivery



Photo 8 – southern berm crest maintenance; topographic activities



PAGE 7 OF 7



Photo 9 – probing activities